


<p>Finding : Item - Parts Missing</p> <p>Finding Date : 04/09/2012</p> <p>Location : Deck Planks -Taped off at time of inspection</p>  <p>Task : Replace missing parts</p>	<p>Medium</p>	<p>10</p>
<p>Surfacing - Grass No remedial maintenance work is required at this time.</p>		
<p>The overall risk for this item at the time of inspection: ‡ For Risk Score see Report Notes</p>	<p>Medium</p>	<p>10</p>